



25729ETree - Removal



25729ETree: Detail view of root excavation down to 6 inches below finished grade



25729ETree: Detail view of root excavation down to 6 inches (+) below finished grade



25729ETree: Detail view of root excavation



25753ETree - Removal



25753ETree: Detail view of root excavation
down to 6 inches below finished grade



25753ETree: Detail view of root excavation down to 6 inches below finished grade



25753ETree: Detail view of large structural root



25753ETree: Detail view of large structural root



25753ETree: Detail view of large structural root



25753ETree: Detail view of root excavation down to 6 inches below finished grade



25725ETree - Removal



25725ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25725ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25725Etree: Detail view of large structural root



25725Etree: Detail view of root excavation down to approx. 6 inches below finished grade



25735ETree - Removal



Inside of curb edge


25735ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25735ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25735ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25735ETree: Detail view of root excavation down to approx. 6 inches below finished grade



25705ETree: Removal



Inside of curb edge

25705ETree: Detail view of proposed curb in proximity to tree trunk